

Fig. 1 Corner Pedestrian Crossing

Fig. 2 MID-STREET PEDESTRIAN CROSSING





Fig. 3 PARK AREA ENTRANCE PLACEMENT

Dublin San Ramon Services District	DATE JAN 2020
STANDARD DETAILS FOR PLACEMENT OF RECYCLED WATER IRRIGATION SIGNS	REVISED BD
SIGNED COPY ON FILE AT DISTRICT OFFICE	DRAWING W-28A