


REMOVAL

FALSE MANHOLE BOTTOM SHALL BE REMOVED AFTER THE FINAL APPURTENANCE ADJUSTMENT INSPECTION. THE PAVING CONTRACTOR AND OWNER'S REPRESENTATIVE WILL COORDINATE THE REMOVAL OF THE FALSE MANHOLE BOTTOMS. CONTRACTOR SHALL REMOVE DEBRIS CAUGHT ON THE FALSE BOTTOM AND NOT ALLOW IT TO DROP INTO MANHOLE.

INSTALLATION AND REMOVAL POSITION NOT TO SCALE



PLAN VIEW NOT TO SCALE

Dublin San Ramon Services District	DATE DEC 2019
MANHOLE: FALSE BOTTOM	DESIGNED RM
SIGNED COPY ON FILE AT DISTRICT OFFICE	DRAWING S-16